Service Bulletin

SB No. ST04100601N

Original Date	Revised Date	Problem Code	Type Code	Status	Author
OCT 6, 2004	-	-	WDUP	NEW	John Morley

Subject: OHDPR8 Spotter Platform Upgrade
Serial Number: ALL

Time Required: ☒15 min ☐30 min ☐45 min ☐1 hr +

Distribute To: ☐Internal ☐Dealer ☐ISO ☐Customer

DESCRIPTION:

The OHDPR8 Spotter Platform has been upgraded.

SOLUTION:

Replace with LEA7601701 as illustrated.



Life Fitness Proprietary and Confidential Information - Only for the Use of the Intended Recipient - Do Not Reproduce or Distribute.